


GVU-3 NO2 MONITOR FIELD WIRING DIAGRAM



TOXALERT GVU-CO, GVU-CO2 AND GVU-VOC SENSORS CAN BE USED IN PLACE OF OR IN COMBINATION WITH TOXALERT NITROGEN DIOXIDE SENSORS. REFER TO APPLICABLE DATA SHEETS AND SCHEMATICS.

Wire Gauge (AWG)	Max Cable Length (feet)	BELDEN NUMBER
18	1,300	8770
16	2,000	8618
14	3,000	83753
12	4,400	83803

SENSOR WIRE GAUGE AND LENGTH (IF CABLE IS NOT RUN IN METAL CONDUIT USE SHIELDED CABLE)

TOXALERT INTERNATIONAL
 GAS DETECTION SYSTEMS
 www.toxalert.com
 P.O. BOX 150 MOUND, MN. 55364
 (952)472-4541

ENG: *
 CONTR: *
 ENG. BY *
 DWN. BY CJS
 R.P.V. A. B. C. D.

GVU-3 NO2 MONITOR- FIELD WIRING
W/ GVU-NO2 SENSORS

*
 SHEET *
 DATE: 5/25/05
 DWG. NO. SECTION 2 STD.