


# GVU-6 NO2 MONITOR FIELD WIRING

## FIELD WIRING DIAGRAM

TOXALERT GVU-CO, GVU-CO2 AND GVU-VOC SENSORS CAN BE USED IN PLACE OF OR IN COMBINATION WITH TOXALERT GVU-NO2 NITROGEN DIOXIDE SENSORS. REFER TO APPLICABLE DATA SHEETS AND SCHEMATICS.



**TOXALERT INTERNATIONAL**  
 GAS DETECTION SYSTEMS  
 www.toxalert.com  
 P.O. BOX 159 MOUND, MN. 55384  
 (952)472-4541

ENG: *	ENG. BY *
CONTR: *	DWN BY <i>CSS</i>
A.	B.
C.	D.

GVU-6 NO2 MONITOR, FIELD WIRING	
*	
*	
SHEET *	DATE: 3/15/06
DWG. NO. SECTION 2 STD.	